

Work Order	Location	Description	Asset	Status	Work Type	Reported Date	Reported By	Priority	Owner	Owner Group
WKU-4646449	AA2-01	Smith East Card Reader Issue, PUT ON BACKLOG 4 PER DAN U. (5/22/26)		ACK	RM	5/21/26 17:12:37	JOSHUA.MUDGETT@WKU.EDU	5		W-BACKLOG4
WKU-4645857	FSH-04-80135	Hole in wall		ACK	RM	5/15/26 15:18:56	HINES.BOWERS@WKU.EDU	5		W-BACKLOG4
WKU-4645832	FSH-03-80096	FSH, room 339, whiteboard needs to be attached back on the wall		ACK	RM	5/15/26 08:22:58	NONSYSUSERWKUKYUS	5		W-BACKLOG4
WKU-4645831	FSH-03	FSH, 3rd floor south wing hole in hallway wall		ACK	RM	5/15/26 08:21:12	NONSYSUSERWKUKYUS	5		W-BACKLOG4
WKU-4645274	NBFCB-01	Flag Pole String At Baseball		ACK	RM	5/7/26 08:24:44	JOSHUA.MUDGETT@WKU.EDU	5		W-BACKLOG4
WKU-4635694	CGC-01	Cravens Library Leaks - routing per Ken		ACK	RM	4/29/26 01:26:23	CADENCE.KIRBY@WKU.EDU	5		W-BACKLOG4
WKU-4635692	CGC-01	Ceiling tile leaking - routing per Ken		ACK	RM	4/29/26 00:21:02	AMBER.HALEY-AFF@WKU.EDU	5		W-BACKLOG4
WKU-4635558	FAC-01	Recital Hall lights fixing - scheduled for Tuesday, Apr 28th, 2026		ACK	NCW	4/24/26 09:48:52	EMILY.LINDSEY@WKU.EDU	5		W-BACKLOG4
WKU-4563981	CGC-09	build trash can loose		ACK	RM	4/23/26 10:11:37	DEBORA.CASTILLO101@TOPPER.WKU.EDU	5		W-BACKLOG4
WKU-4563944	HTB-01	Outdoor outlet not working		ACK	NCW	4/22/26 12:18:11	SHERRY.WEST@WKU.EDU	5		W-BACKLOG4
WKU-4563792	EBS-03	EBS - 3rd floor Hallway have several ceiling tiles that have water stains on them		ACK	NCW	4/20/26 09:29:01	TAMMY.PRICE@WKU.EDU	5		W-BACKLOG4
WKU-4563780	HSB-01	Health Services		ACK	RM	4/20/26 00:33:52	NANCY.MILLER@WKU.EDU	5		W-BACKLOG4
WKU-4561935	FSH-02-80031	KB - FSH / Gatton 221 & 222 - Door Hardware Installation for Lock		ACK	RM	4/2/26 21:06:56	NOAH.WILLS@WKU.EDU	5		W-BACKLOG4
WKU-4561854	AAC-03	Toilet Tissue Dispenser lock broke		ACK	NCW	4/2/26 02:56:07	CLAUDETTE.CRAVEN@WKU.EDU	5		W-BACKLOG4
WKU-4561936	CGC-04	Loud ticking sound in ceiling, Cravens 4th floor		ACK	NCW	4/1/26 09:59:21	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4560737	AA1-02-72357	Door Locks Lack Interior Lock		ACK	RM	3/24/26 12:27:38	HUNTER.SHECKELLS@WKU.EDU	5		W-BACKLOG4
WKU-4491030	CGC-03	Helim 3rd floor window ceiling leak		ACK	RM	3/19/26 01:03:15	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4490955	CGC-02	CGC, LEAKS FROM STORM, FROM 2ND FLOOR TO GROUND FLOOR, NO SPECIFIC AREA		ACK	RM	3/16/26 07:44:39	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4490972	CGC-01	water leaking		ACK	RM	3/16/26 07:00:57	DEBORA.CASTILLO101@TOPPER.WKU.EDU	5		W-BACKLOG4
WKU-4490971	GWH-01	Door leaking		ACK	RM	3/16/26 01:16:05	NANCY.MILLER@WKU.EDU	5		W-BACKLOG4
WKU-4490500	KYB-01	Roof leak Kentucky Building		ACK	NCW	3/10/26 16:14:57	CHARLES.HURST@WKU.EDU	5		W-BACKLOG4
WKU-4561885	CHL-03-67230	Cravens 4th floor stairwell door needs to be painted		ACK	NCW	3/5/26 15:55:18	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4561884	CHL-03-67230	Helim 2nd floor epoxy starting to break		ACK	NCW	3/4/26 14:50:08	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4490327	CGC-EXT-02680	AJ - KB - Cravens bridge showing cracks - BACKLOG4 PER ANGIE		ACK	NCW	3/4/26 14:29:32	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4477182	AA2-EXT-01735	MECH15-M Maintenance Of Backflow Preventer	WKU-70403 SCHED	PM		2/21/26 20:19:54	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4406581	TRACKCS-01-82097	MECH15-M Maintenance Of Backflow Preventer	WKU-82099 SCHED	PM		2/21/26 11:28:03	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4406533	PPSCWB-01-82131	MECH15-M Maintenance Of Backflow Preventer	WKU-21597 SCHED	PM		2/21/26 11:27:26	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4406002	NBF-EXT-BF	MECH15-M Maintenance Of Backflow Preventer	WKU-10761 SCHED	PM		2/21/26 11:21:43	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4405599	AA2W-01-20001	MECH15-M Maintenance Of Backflow Preventer	WKU-70350 SCHED	PM		2/21/26 11:17:28	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4403219	PS1-01	Red floor at Facilities Management		ACK	RM	2/12/26 00:55:56	AMBER.HALEY-AFF@WKU.EDU	5		W-BACKLOG4
WKU-4403122	GWH-01	Studio A Gordon Wilson Hall Damages on Wall - BACKLOG4 PER KEN		ACK	RM	2/10/26 15:14:58	KATHY.FARRIS@WKU.EDU	5		W-BACKLOG4
PRB26-162	KYB	PRB26-162 KY Building, Room- KY Museum- estimate to remove existing floor and replace with something else		ACK	PROJ	2/4/26 08:09:14	AMY.PATTERSON@WKU.EDU	5		W-BACKLOG1
WKU-4336658	AA2W-01-20001	MECH15-M Maintenance Of Backflow Preventer	WKU-70338 SCHED	PM		1/26/26 03:07:23	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4247814	AA2-01-20086	MECH15-M Maintenance Of Backflow Preventer	WKU-70402 SCHED	PM		12/29/25 01:27:29	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4247766	AA2-01-20086	MECH15-M Maintenance Of Backflow Preventer	WKU-70401 SCHED	PM		12/29/25 01:26:47	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4247742	AA1-01-12103	MECH15-M Maintenance Of Backflow Preventer	WKU-09398 SCHED	PM		12/29/25 01:26:24	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-4161793	JJ-01-01764	JJ, Room 114, door locking on both sides and need it to not lock on the inside		ACK	RM	11/21/25 10:12:40	DANIEL.BURCH@WKU.EDU	5		W-BACKLOG4
WKU-4161579	CEC-01-11800	CEC/121/DESK IS COMING APART/NEEDS TIGHTENING/HAS A BAD SQUAKE		ACK	RM	11/18/25 16:00:09	MICHELE.HOSKINS@WKU.EDU	5		W-BACKLOG4
WKU-4161471	PHAC-01-73257	Break Room		ACK	RM	11/17/25 10:36:09	LINZIE.TATE@WKU.EDU	5		W-BACKLOG4
WKU-4160151	JRH-01-48701	JRH, EINSTEIN BAGELS, CEILING IN AREA IS SEVERLY DAMAGED		ACK	RM	11/6/25 08:06:42	KRISTINA.MORROW560@TOPPER.WKU.EDU	5		W-BACKLOG4
WKU-4160066	AA1-01	Diddle Weight Room Hand Sanitizer Dispenser		ACK	RM	11/4/25 15:48:29	JOSHUA.MUDGETT@WKU.EDU	5		W-BACKLOG4
WKU-4159529	WAB-GR-12073	Raise cabinets in office G01A		ACK	RM	10/31/25 10:55:19	AMY.FUGAT@WKU.EDU	5		W-BACKLOG4
WKU-4327816	KYB-EXT-49557	Powerwashing exterior light globes in Kentucky Building Courtyard		ACK	PROJ	10/24/25 11:04:04	BRENT.BJORKMAN@WKU.EDU	5		W-BACKLOG4
WKU-4082210	CHL-02	Helim 2nd floor womens room stall door doesn't close		ACK	RM	10/9/25 09:09:47	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4081674	CCS-01	ISV #5/Colonial Court #5 Reoccurring Electric Issue		ACK	RM	10/2/25 08:00:25	HOUSTON.HIX@WKU.EDU	5		W-BACKLOG4
WKU-4040904	HSB-01	HSB, sign out front is leaning and needs fixed		ACK	RM	9/23/25 09:19:52	SHELBY.HANDLEY@WKU.EDU	5		W-BACKLOG4
WKU-4002891	CHL-02	Helim floor outlet covers broken		INPRG	RM	9/4/25 12:18:25	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-4001976	CHL-03	Helim 3002/3008 room divider doesn't close		ACK	RM	8/27/25 09:18:38	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3905567	CHL-03	Helim 3rd fl mens room stall doesn't close		ACK	RM	8/15/25 10:50:24	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3905564	CHL-02	Helim 2nd fl womens room stall doesn't shut		ACK	RM	8/15/25 10:46:48	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3905562	CHL-01	Helim 1st fl mens room stall doesn't shut		ACK	RM	8/15/25 10:42:04	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3889376	PPB-01-00023	PPB, Paint Shop - The paint shop needs better lighting, Per Ken, all LED lighting throughout the entire shop an		ACK	RM	7/28/25 10:03:10	NONSYSUSERWKUKYUS	5		W-BACKLOG4
WKU-3888078	PPB-01-00027-CL	PPB, Stockroom/Office - The stockroom and stockroom office need better lighting, Per Ken, the entire area sh		ACK	RM	7/28/25 09:45:33	NONSYSUSERWKUKYUS	5		W-BACKLOG4
WKU-3862136	EBS-02-70062	"NM" - EBS 2127 - Carpet is loose and is bubbled up. This is a tripping hazard.		ACK	RM	7/28/25 08:22:12	TAMMY.PRICE@WKU.EDU	5		W-BACKLOG4
WKU-3826637	AAC-EXT-48878	Sidewalk Collapse		ACK	RM	7/17/25 08:58:35	ZACHARY.MARCUM@WKU.EDU	5		W-BACKLOG4
WKU-3825515	IED-EXT-00371	Courtyard gazebo outside of West lobby has structural damage		ACK	RM	7/2/25 14:37:24	CANDI.BOEHMER@WKU.EDU	5		W-BACKLOG4
WKU-3818425	AAC-02-82226	AAC		ACK	RM	6/25/25 20:20:25	CLAUDETTE.CRAVEN@WKU.EDU	5		W-BACKLOG4
WKU-3810217	CREASONSC-01-00248	MECH15-M Maintenance Of Backflow Preventer	WKU-29275 SCHED	PM		6/23/25 15:22:10	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3810193	AA1-01-29273	MECH15-M Maintenance Of Backflow Preventer	WKU-29795 SCHED	PM		6/23/25 15:21:49	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3804944	PHAC-BS-21071	MECH15-M Maintenance Of Backflow Preventer	WKU-70407 SCHED	PM		6/23/25 14:13:59	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3758579	JRH-01-14726	MECH15-M Maintenance Of Backflow Preventer	WKU-29794 SCHED	PM		6/23/25 03:55:40	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3756835	HSB-01-72700	MECH15-M Maintenance Of Backflow Preventer	WKU-29568 SCHED	PM		6/23/25 03:34:00	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3756787	AA1-01-72465	MECH15-M Maintenance Of Backflow Preventer	WKU-10326 SCHED	PM		6/23/25 03:33:21	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3747130	JRH-01-14726	MECH15-M Maintenance Of Backflow Preventer	WKU-66354 SCHED	PM		6/23/25 01:34:05	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3747106	JRH-01-14726	MECH15-M Maintenance Of Backflow Preventer	WKU-13466 SCHED	PM		6/23/25 01:33:42	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3747082	IMF-EXT-02261	MECH15-M Maintenance Of Backflow Preventer	WKU-29272 SCHED	PM		6/23/25 01:33:23	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3747058	IMF-EXT-02261	MECH15-M Maintenance Of Backflow Preventer	WKU-29271 SCHED	PM		6/23/25 01:33:04	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3747034	IMF-01-03901	MECH15-M Maintenance Of Backflow Preventer	WKU-10877 SCHED	PM		6/23/25 01:32:45	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3746986	HSB-01-72700	MECH15-M Maintenance Of Backflow Preventer	WKU-29576 SCHED	PM		6/23/25 01:32:07	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3746962	HSB-01-72700	MECH15-M Maintenance Of Backflow Preventer	WKU-29567 SCHED	PM		6/23/25 01:31:47	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3746771	AA1-01-72397	MECH15-M Maintenance Of Backflow Preventer	WKU-10290 SCHED	PM		6/23/25 01:29:17	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3745351	VMH-01-12649	Van Meter door lock needs repaired		ACK	RM	6/13/25 12:06:44	SARAH.THOMAS@WKU.EDU	5		W-BACKLOG4
WKU-3745164	AA1-01-72541	DO NOT ROUTE - Smith West Doors Malfunctioning		ACK	NCW	6/9/25 15:49:52	JOSHUA.MUDGETT@WKU.EDU	5		W-BACKLOG4
WKU-3676820	AA2W-01	Smith Stadium West Batteries Depleted		ACK	RM	5/19/25 08:50:43	JOSEPH.FREDRICK@WKU.EDU	5		W-BACKLOG4
WKU-3676819	AA2-01	Smith Stadium East Batteries Depleted		ACK	RM	5/19/25 08:47:25	JOSEPH.FREDRICK@WKU.EDU	5		W-BACKLOG4
WKU-3676271	PPB-01	Ceiling Tiles		ACK	RM	5/13/25 00:53:33	AMBER.HALEY-AFF@WKU.EDU	5		W-BACKLOG4
WKU-3670514	SSB-EXT-03266	MECH15-M Maintenance Of Backflow Preventer	WKU-10812 SCHED	PM		4/28/25 19:18:08	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3667832	AA2-01-28404	MECH15-M Maintenance Of Backflow Preventer	WKU-66400 SCHED	PM		4/28/25 14:43:13	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3612343	SSB-02-10836	MECH15-M Maintenance Of Backflow Preventer	WKU-70420 SCHED	PM		4/28/25 03:53:05	MTCCCRON_WKUKYUS	4		W-BACKLOG1
WKU-3675736	PPB-EXT-00041	DO NOT ROUTE YET - The curb, outside of DFM by the back gate has a piece broken off.		ACK	RM	4/14/25 11:49:27	NANCY.MORRIS801@TOPPER.WKU.EDU	5		W-BACKLOG4
WKU-3600020	HCIC-01-83852	Crack in restroom floor		ACK	RM	4/9/25 14:06:42	SPENCER.ANDERSON@WKU.EDU	5		W-BACKLOG4
WKU-3599975	AA1-01	Diddle - Jaguar Ride on need wheels replaced. (Wheels are in the cage) first fl ramp by 3		ACK	RM	4/9/25 08:13:13	KOZABOZEV	5		W-BACKLOG4
WKU-3599112	CGC-08-02758	Cravens 8th floor /806 water leak		ACK	RM	4/4/25 10:08:55	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3599062	CGC-05-02717	Water leaked into Cravens 502 from rain		ACK	RM	4/3/25 14:58:26	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3599046	CC4-01	ISV5/Colonial Court #5 GFCl Issue		ACK	RM	4/3/25 13:26:06	HOUSTON.HIX@WKU.EDU	5		W-BACKLOG4
WKU-3598772	CGC-05-02717	Cravens 502 water from rain		ACK	RM	3/31/25 15:03:41	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3523601	GRH-01-21163	GRH 3029 - window condensation		ACK	RM	2/27/25 07:36:57	TAMMY.SPINKS@WKU.EDU	5		W-BACKLOG4
WKU-3477332	CHL-02	5 floor outlets cover broken or missing in Helim		ACK	RM	2/24/25 12:05:09	DANIEL.PEACH@WKU.EDU	5		W-BACKLOG4
WKU-3431155	GRH-03	GARH 3rd floor office suite, there are several stained and damaged ceiling tiles and leaks that has the occup								

WKU-2936406	FAC-01-02338	unsafe ceiling tile and light covers at FAC rooms 180 and 182.	ACK	SAF	8/7/24 12:19:25	CATHERINE.CABRERA@WKU.EDU	3	W-BACKLOG4
WKU-2923139	FAC-02-02452	water stain on the light cover at FAC room 257.	ACK	RM	8/6/24 06:55:57	CATHERINE.CABRERA@WKU.EDU	5	W-BACKLOG4
WKU-2853755	JJ-01-01799	JJH 122 - Dryer vent needs to be cleaned out	ACK	RM	7/18/24 14:30:07	HOLLY.HATCHER@WKU.EDU	5	W-BACKLOG4
WKU-2853519	FSH-04-80151	Galton 406 Bathroom Light Debris	ACK	RM	7/12/24 19:41:42	JACOB.BOWEN@WKU.EDU	5	W-BACKLOG4
WKU-2852095	JRH-03-72909	JRH, 350, CARPET IS BUBBLING UP	ACK	RM	7/5/24 12:20:11	STEVE.LANCASTER@WKU.EDU	5	W-BACKLOG4
WKU-2852000	GWH-EXT-00198	Waterspout Eroded Concrete Spot-Gordon Wilson Hall	INPRG	PRO	7/2/24 08:52:18	MTAYLORWKUEZ	5	W-BACKLOG4
WKU-2851984	GRH-03-21312	Window condensation in GRH 3076 (classroom)	ACK	RM	7/1/24 15:29:54	TAMMY.SPINKS@WKU.EDU	5	W-BACKLOG4
WKU-2803819	GRH-03-21329	Condensation in window pane - GRH 3094	REC	RM	6/24/24 08:57:27	TAMMY.SPINKS@WKU.EDU	5	W-BACKLOG4
WKU-2772003	JRH-03-82598	Park and Ride parking lot pedestal GFI outlet	ACK	RM	6/21/24 13:18:14	GARY.SPINKLE@WKU.EDU	5	W-BACKLOG4
WKU-2698760	GRH-03-21363	GRH 3036 suite door would not unlock with ID card prior to 7:30am	ACK	RM	5/6/24 14:45:36	TAMMY.SPINKS@WKU.EDU	5	W-BACKLOG4
WKU-2697923	HCIC-01	HCIC, BALL ROOM, Large blinds broken, 2 of the blinds on the huge windows are broken. This is causing prob	INPRG	RM	4/30/24 18:26:51	NAOMI.ROWLAND@WKU.EDU	5	W-BACKLOG4
WKU-2276910	PPB-01-00016	Semi Annual Class 0 safety cert.	ACK	SAF	12/15/23 12:28:41	DANIEL.UHLS@SODEXO.COM	5	W-BACKLOG1
WKU-2221335	SSB-01	Receiving Dock Latch Bolt Monitor not working properly - SEE DETAILS	ACK	RM	10/31/23 11:08:25	JOSEPH.FREDRICK@WKU.EDU	5	W-BACKLOG3
WKU-2054827	COHH-EXT	COHH, uneven sidewalk in front of the COHH 3r floor facing Cherry Hall	ACK	RM	9/11/23 08:29:09	CATHERINE.CABRERA@WKU.EDU	3	W-BACKLOG4
WKU-1941367	HIL-02-16535	STR - HIL, 236, Sections of my baseboards in my room have been missing/damaged since I moved in last Fall	REC	PROJ	7/24/23 07:25:01	RICHARD.PIKE342@TOPPER.WKU.EDU	5	WKU-HOLD
WKU-1409570	KYB-01	Kentucky Building- SEE DETAILS	ACK	RM	1/25/23 11:28:03	KEVIN.GUTIERREZ@WKU.EDU	5	W-BACKLOG4
WKU-1082704	RH-01	Rodes-Vending area re tile	INPRG	PRO	9/16/22 14:58:08	CKOZABOEZ	5	WKU-HOLD
WKU-981900	PPB-01-00044	TEST	RESPONDED	RM	8/16/22 12:28:33	ANGIE.JACKSON@WKU.EDU	5	WKU-HOLD
WKU-753848	PPB-01-00044	Dimmer to be installed in Ken and Angies office 2nd request	INPRG	PRO	4/28/22 15:14:04	LCAMPBELLEZ	5	W-BACKLOG1
WKU-326022	1355-EXT-49802	Awning has torn apart from the storm	RESPONDED	RM	12/6/21 11:45:08	CHESTER.MCNULTY@WKU.EDU	5	WKU-HOLD
WKU-325197	DSU-RF	Outdoor Warning System - DSU	RESPONDED	RM	11/30/21 10:40:57	DERECK.KEELING@WKU.EDU	5	W-BACKLOG1