

Master Asbestos Location List

~ This list shall be referenced prior to any work which may disturb any building or insulating materials ~

All black mastics, along with all other suspect materials, are presumed asbestos-containing until sufficient sampling has been completed to prove otherwise.

Always check with WKU Environment, Health & Safety @ 745-2236 before disturbing a building material if you are not sure about its asbestos content.

This list is compiled and maintained by Laura Tomlin, please direct questions, corrections, or concerns to: [WKU Asbestos Program Coordinator](#)

Campus Locations	Building Materials									Insulating Materials						Notes
	Ceiling Materials	Ceiling Tile	Flooring, Covebase, or Mastic	Hard Plaster	Wall Board/Joint Compound	Window Pane Glaze / Frame Caulk	Roofing Materials	Roof Flashing	Fire Doors	Pipes and/or Fittings	Water Heater, Tank or Boiler Jacket	Chiller Jacket	Cooling Towers	Packings & Gaskets		
1 Academic Complex	SAFE	SAFE	A	SAFE	SAFE & 1	SAFE	A	A	SAFE	A	A	n/a	n/a	presumed	1, 5, 12, 14	
2 Agra-Expo Center	SAFE	SAFE	A	SAFE	SAFE	A	A	A	presumed	SAFE	SAFE	n/a	n/a	presumed	5	
3 Alumni House	SAFE	SAFE	A	SAFE	SAFE	A	SAFE	SAFE	n/a	A	SAFE	n/a	n/a	presumed		
4 Barnes-Campbell Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	
5 Bates-Runner Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE		
6 Bemis Lawrence Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	SAFE	n/a	presumed	
7 Cherry Hall	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	A	SAFE	SAFE	SAFE	SAFE	presumed	
8 Complex Eng & Bio Science	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	
9 Cravens Grad. Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	presumed	SAFE	A	A	SAFE	SAFE	SAFE	presumed	
10 Dairy Barn	SAFE & 15	n/a	SAFE	SAFE	SAFE	SAFE	presumed	presumed	n/a	SAFE	SAFE	n/a	n/a	presumed	15	
11 Diddle Arena	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	A	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	
12 Downing University Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	
13 Environmental Sci. & Tech	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	presumed	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	
14 Faculty House	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	presumed		
15 Fine Arts Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	A	A	A	SAFE	SAFE	SAFE	presumed	
16 Foundation Building	SAFE & 3	A	A	SAFE	SAFE	presumed	A	A	A	A	SAFE	n/a	n/a	presumed	3	
17 Garrett Conference Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	presumed	presumed	A	SAFE	SAFE	SAFE	SAFE	presumed	
18 Gilbert Hall	SAFE	SAFE	A	SAFE	SAFE	A	SAFE	SAFE	SAFE	A & 9	SAFE	SAFE	SAFE	SAFE	presumed	
19 Gordon Wilson Hall	SAFE	SAFE	A	SAFE	presumed	A	presumed	presumed	presumed	A	SAFE	n/a	n/a	presumed		
20 Grise Hall	SAFE	SAFE	A	SAFE	SAFE	A	A	A	SAFE	A	A	SAFE	SAFE	SAFE	presumed	
21 Hardin Planetarium	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	n/a	n/a	presumed		
22 Hazardous Waste Building	n/a	n/a	n/a	n/a	n/a	n/a	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	presumed		
23 Helm Library	SAFE	SAFE	A	SAFE	SAFE	A	presumed	presumed	A	A	SAFE	SAFE	SAFE	SAFE	presumed	
24 Honors Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	4	
25 Hugh Poland Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	A	SAFE	n/a	SAFE	presumed	16	
26 Industrial Ed. Building	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	SAFE	SAFE	n/a	n/a	presumed	5	
27 International Center	presumed	presumed	presumed	presumed	presumed	A	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed		
28 Jones Jagers	SAFE	SAFE	A	SAFE	SAFE	A & 16	presumed	presumed	SAFE	A	SAFE	n/a	n/a	presumed	5, 12, 13, 16	

"A" - the material is asbestos-containing and should not be disturbed.

"presumed" - the material is presumed to contain asbestos and has not been sufficiently sampled to prove otherwise ~ DO NOT DISTURB ~ without prior approval.

"SAFE" - the material does not contain asbestos.

"n/a" - not applicable.

NOTES:

- | | | | |
|--|--|--|---|
| (1) Sound control wall panels in radio & TV studios only | (5) Some lab table tops contain asbestos | (9) Asbestos-containing black pipe-coating | (13) Asbestos lighting/heating insulation |
| (2) Spray applied ceiling in 205, 208 & 211 only | (6) Welding tables may contain asbestos | (10) Asbestos-containing wiring insulation | (14) Asbestos-containing window/door panels |
| (3) Vault ceiling plaster only is asbestos | (7) Asbestos-containing chalkboards | (11) Asbestos-containing asphalt siding | (15) Asbestos cementitious board or siding |
| (4) Asbestos-containing duct or vent insulation/tape | (8) Asbestos cementitious pipe or vent | (12) Asbestos-containing glue-dots | (16) Asbestos-containing caulking |

This list is a review of asbestos data intended for reference use only. An Asbestos Management Request and full NESHAP asbestos survey are required prior to any demolition or renovation activity.

WKU Master Asbestos Location List

November 19, 2008

Campus Locations	Building Materials									Insulating Materials						Notes
	Ceiling Materials	Ceiling Tile	Flooring, Covebase, or Mastic	Hard Plaster	Wall Board/Joint Compound	Window Pane Glaze / Frame Caulk	Roofing Materials	Roof Flashing	Fire Doors	Pipes and/or Fittings	Water Heater, Tank or Boiler Jacket	Chiller Jacket	Cooling Towers	Packings & Gaskets		
29 Keen Hall	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	presumed	SAFE	A	SAFE	SAFE	SAFE	presumed	12, 16	
30 Kentucky Building	SAFE	SAFE	A	SAFE	SAFE	A & 16	SAFE	SAFE	presumed	A	A	SAFE	A	presumed	5	
31 Mass Media & Tech Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE		
32 McCormack Hall	SAFE	SAFE	A	SAFE	SAFE	SAFE & 16	SAFE	SAFE	SAFE	SAFE	SAFE & 9	SAFE	n/a	presumed	9, 16	
33 McLean Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE	
34 Meredith Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	
35 Minton Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	A	SAFE	SAFE	SAFE	presumed		
36 North/East Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE	
37 Parking & Transport Bldg.	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE	
38 Pearce Ford Tower	A	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	A & 9	SAFE	n/a	n/a	presumed	9, 12
39 Physical Plant	SAFE	SAFE	A	SAFE	SAFE	A	A	A	presumed	A	SAFE	SAFE	n/a	n/a	presumed	
40 Police Station	SAFE	SAFE	A	SAFE	SAFE	A	A	A	presumed	A	SAFE	SAFE	n/a	n/a	presumed	
41 Potter Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	
42 Preston Health Center	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	
43 Rock House	presumed	SAFE	A	presumed	presumed	SAFE	SAFE	SAFE	n/a	A	SAFE	SAFE	n/a	n/a	presumed	
44 Rodes Harlin Hall	SAFE	SAFE	A	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	A & 9	SAFE	SAFE	SAFE	presumed	9
45 Schneider Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	
46 Science & Tech Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE	
47 Smith Stadium East	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	SAFE	SAFE	n/a	n/a	presumed	
48 South Campus	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	
49 South/West Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE	
50 Steam Dist. System	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	A	n/a	n/a	n/a	presumed	
51 Steam Plant	SAFE	SAFE	SAFE	SAFE	SAFE	A	A	A	n/a	A	A	n/a	n/a	n/a	presumed	
52 Supply - Services Bldg.	SAFE	SAFE	A	SAFE	SAFE	presumed	SAFE	SAFE	presumed	A	SAFE	SAFE	n/a	n/a	presumed	
53 Tate Page Hall	SAFE	SAFE	A	SAFE	SAFE	presumed	presumed	presumed	presumed	A	SAFE	SAFE	n/a	n/a	presumed	5, 13, 14
54 Taylor Center	SAFE	SAFE	A	SAFE	SAFE	SAFE	presumed	presumed	SAFE	presumed	SAFE	SAFE	n/a	n/a	n/a	13
55 TCCW	SAFE & 2	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	A	SAFE	SAFE	SAFE	A	presumed	2, 5, 7, 12, 14
56 TCNW	SAFE	SAFE	A	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	A	SAFE	SAFE	SAFE	SAFE	presumed	7, 12
57 Van Meter Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	presumed	
58 WKU Center	SAFE	SAFE	A	SAFE	SAFE	SAFE & 16	SAFE	SAFE	presumed	A	SAFE	SAFE	n/a	n/a	presumed	15, 16
59 Wetherby Admin. Building	SAFE	SAFE	A	SAFE	SAFE	presumed	SAFE	SAFE	presumed	A	SAFE	SAFE	n/a	n/a	presumed	13, 14
60 Zacharias Hall	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	presumed	

"A" - the material is asbestos-containing and should not be disturbed.

"presumed" - the material is presumed to contain asbestos and has not been sufficiently sampled to prove otherwise ~ DO NOT DISTURB ~ without prior approval.

"SAFE" - the material does not contain asbestos.

"n/a" - not applicable.

NOTES:

- | | | | |
|--|--|--|---|
| (1) Sound control wall panels in radio & TV studios only | (5) Some lab table tops contain asbestos | (9) Asbestos-containing black pipe-coating | (13) Asbestos lighting/heating insulation |
| (2) Spray applied ceiling in 205, 208 & 211 only | (6) Welding tables may contain asbestos | (10) Asbestos-containing wiring insulation | (14) Asbestos-containing window/door panels |
| (3) Vault ceiling plaster only is asbestos | (7) Asbestos-containing chalkboards | (11) Asbestos-containing asphalt siding | (15) Asbestos cementitious board or siding |
| (4) Asbestos-containing duct or vent insulation/tape | (8) Asbestos cementitious pipe or vent | (12) Asbestos-containing glue-dots | (16) Asbestos-containing caulking |

This list is a review of asbestos data intended for reference use only. An Asbestos Management Request and full NESHAP asbestos survey are required prior to any demolition or renovation activity.

WKU Master Asbestos Location List HOUSES and MISCELLANEOUS BUILDINGS

Campus Locations	Building Materials								Insulating Materials							Notes
	Ceiling Materials	Ceiling Tile	Flooring, Covebase, or Mastic	Hard Plaster	Wall Board/Joint Compound	Window Pane Glaze / Frame Caulk	Roofing Materials	Roof Flashing	Fire Doors	Pipes and/or Fittings	Water Heater, Tank or Boiler Jacket	Chiller Jacket	Cooling Towers	Packings & Gaskets		
1 Baseball Press Box	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE			
2 Colonial Court #2	SAFE	n/a	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	
3 Colonial Court #3	SAFE	n/a	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	
4 Farm House # 1	presumed	presumed	presumed	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	n/a	presumed	
5 Farm House # 2	presumed	presumed	presumed	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	n/a	presumed	
6 Farm House # 3	presumed	presumed	presumed	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	n/a	presumed	
7 Farm House # 4	presumed	presumed	presumed	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	n/a	presumed	
8 Farm House # 5	SAFE	n/a	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	11
9 Farm House # 6	presumed	presumed	presumed	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	n/a	presumed	
10 Farm (Green Shop)	presumed	presumed	presumed	presumed	presumed	n/a	n/a	n/a	n/a	presumed	presumed	n/a	n/a	presumed		
11 Farm (Hog Barn)	SAFE	n/a	SAFE	n/a	SAFE & 15	n/a	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	15
12 Felts Log Cabin	n/a	n/a	n/a	n/a	n/a	SAFE	SAFE	n/a	n/a	SAFE	n/a	n/a	n/a	n/a	n/a	
13 Forrest Dr. Coal Analysis	SAFE	n/a	n/a	n/a	n/a	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	n/a	n/a	n/a	
14 Indoor Batting Bldg.	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE		
15 Intramural Complex	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	n/a	SAFE		
16 Log Cabin (14th Avenue)	presumed	presumed	presumed	SAFE	SAFE	presumed	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed	presumed	
17 1700 Chestnut Street	SAFE	SAFE	A	SAFE	SAFE	A	presumed	presumed	n/a	presumed	SAFE	n/a	n/a	n/a	n/a	4, 13
18 1783 Chestnut Street	SAFE	n/a	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	4, 8
19 1702 Normal Drive	SAFE	SAFE	A	SAFE	SAFE	A	SAFE	SAFE	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	15
20 1790 Normal Drive	presumed	presumed	A	presumed	presumed	presumed	SAFE	SAFE	n/a	presumed	presumed	n/a	n/a	presumed		
21 1716 Park Street	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	A	SAFE	n/a	A	presumed	n/a	n/a	presumed		
22 501 Regents Ave,	SAFE	n/a	presumed	SAFE	SAFE	SAFE	presumed	presumed	n/a	presumed	presumed	n/a	n/a	n/a	n/a	4
23 513 Regents Ave.	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	SAFE	presumed	n/a	SAFE	SAFE	n/a	n/a	n/a	n/a	4
24 205 South Way	presumed	presumed	presumed	presumed	presumed	presumed	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed	presumed	
25 1425 State Street	presumed	presumed	presumed	presumed	presumed	presumed	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed	presumed	
26 1532 State Street	presumed	presumed	presumed	presumed	presumed	presumed	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed	presumed	4, 13
27 1536 State Street	presumed	presumed	presumed	presumed	presumed	presumed	presumed	presumed	n/a	presumed	presumed	n/a	n/a	presumed	presumed	
28 1818 U.S. 31-W By-Pass	SAFE	n/a	SAFE	SAFE	SAFE	SAFE	presumed	SAFE & 16	SAFE	n/a	SAFE	SAFE	n/a	n/a	SAFE	8, 15, 16

"A" - the material is asbestos-containing and should not be disturbed.

"presumed" - the material is presumed to contain asbestos and has not been sufficiently sampled to prove otherwise ~ DO NOT DISTURB ~ without prior approval.

"SAFE" - the material does not contain asbestos.

"n/a" - not applicable.

NOTES:

- | | | | |
|--|--|--|---|
| (1) Sound control wall panels in radio & TV studios only | (5) Some lab table tops contain asbestos | (9) Asbestos-containing black pipe-coating | (13) Asbestos lighting/heating insulation |
| (2) Spray applied ceiling in 205, 208 & 211 only | (6) Welding tables may contain asbestos | (10) Asbestos-containing wiring insulation | (14) Asbestos-containing window/door panels |
| (3) Vault ceiling plaster only is asbestos | (7) Asbestos-containing chalkboards | (11) Asbestos-containing asphalt siding | (15) Asbestos cementitious board or siding |
| (4) Asbestos-containing duct or vent insulation/tape | (8) Asbestos cementitious pipe or vent | (12) Asbestos-containing glue-dots | (16) Asbestos-containing caulking |

This list is a review of asbestos data intended for reference use only. An Asbestos Management Request and full NESHAP asbestos survey are required prior to any demolition or renovation activity.