

# Work Order List

Site: WKUKYUS											
Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
WKU-2054827	COHH, uneven sidewalk in front of the COHH 3r floor facing Cherry Hall	RM	ACK	3		COHH-EXT				9/19/23	12/19/23
WKU-2221335	Receiving Dock Latch Bolt Monitor not working properly - SEE DETAILS	RM	ACK	5		SSB-01				11/7/23	11/7/23
WKU-2539312	FARMERS MARKET, SIDE DOOR BETWEEN ALLEY AND MEXICAN RESTURANT, DOOR IS BROKEN AND ALMOST FALLING OFF	RM	ACK	5		HER-EXT				3/5/24	3/5/24
WKU-2697923	HCIC, BALL ROOM, Large blinds broken, 2 of the blinds on the huge windows are broken. This is causing problems when using the room.	RM	INPRG	5		HCIC-01				5/7/24	7/25/24
WKU-2698760	GRH 3036 suite door would not unlock with ID card prior to 7:30am	RM	ACK	5		GRH-03-2131				5/13/24	5/13/24
WKU-2772003	Park and Ride parking lot pedestal GFI outlet	RM	ACK	5		JRH-03-8259				6/28/24	6/28/24
WKU-2803819	Condensation in window pane - GRH 3094	RM	REC	5		GRH-03-2131				7/11/24	2/27/25
WKU-2851984	Window condensation in GRH 3076 (classroom)	RM	ACK	5		GRH-03-2131				7/24/24	7/24/24
WKU-2852000	Waterspout Eroded Concrete Spot-Gordon Wilson Hall	PRO	INPRG	5		GWH-EXT-00198				7/2/24	7/3/24
WKU-2852095	JRH, 350, CARPET IS BUBBLING UP	RM	ACK	5		JRH-03-7290				7/12/24	7/15/24
WKU-2853519	Gatton 406 Bathroom Light Debris	RM	ACK	5		FSH-04-8015				7/19/24	7/19/24
WKU-2853755	JJH 122 - Dryer vent needs to be cleaned out	RM	ACK	5		JJ-01-01799				7/25/24	7/25/24
WKU-2923139	water stain on the light cover at FAC room 257.	RM	ACK	5		FAC-02-0245				8/6/24	8/6/24
WKU-2936406	unsafe ceiling tile and light covers at FAC rooms 180 and 182.	SAF	ACK	3		FAC-01-0233				8/8/24	8/16/24
WKU-2937827	SC, Room C231, wall paneling needing to be out back up - Spoke w/ Donna (Warren Co Public Schools) per Donna, Justin aware	RM	ACK	5		SC-01-00321				8/22/24	8/22/24
WKU-3036686	Helm 2nd floor countertop chipping	RM	ACK	5		CHL-02				9/4/24	9/4/24
WKU-3039742	Air Compressor Repair	RM	ACK	5		PS3-01				9/26/24	9/26/24
WKU-3039791	Access Systems	RM	ACK	5		SC-01				9/27/24	9/27/24
WKU-3199407	Commons - deficiencies - relocate 2 smoke detectors - see details	RM	ACK	5		CHL-BS				11/18/24	11/18/24
WKU-3199520	The floor is cracked next to the room 2007 at the Commons 2nd floor.	RM	ACK	3		CHL-02				11/13/24	11/13/24
WKU-3199528	Helm 2nd floor mens room, doors don't shut	RM	ACK	5		CHL-02				11/19/24	11/19/24
WKU-3199529	Helm 3rd floor mens room stall door	RM	ACK	5		CHL-03				11/19/24	11/19/24
WKU-3199530	Helm 2nd floor womens room, stall door	RM	ACK	5		CHL-02				11/19/24	11/19/24
WKU-3199531	Helm 1st floor womens room, stall doors	RM	ACK	5		CHL-01				11/19/24	11/19/24
WKU-3199532	Helm 1st floor mens room, stall door	RM	ACK	5		CHL-01				11/19/24	11/19/24
WKU-3200454	PH, Room 127, ceiling tile replacement	RM	ACK	5		PH-01-02993				11/25/24	11/25/24
WKU-325197	Outdoor Warning System - DSU	RM	RESPONDI	5		DSU-RF				5/21/25	5/21/25
WKU-3253006	Multiple issues with Museum Storage Doors	NCW	ACK	5		SSB-02-1083				12/18/24	12/18/24
WKU-3335871	DSU 1ST FLOOR 1074 Disability	RM	ACK	5		DSU-01-8297				1/14/25	1/14/25
WKU-3335907	Water standing in between window panes - GRH 3094	RM	RESPONDI	5		GRH-03-2131				1/15/25	1/15/25
WKU-3360316	Helm 3rd floor window leak	RM	ACK	5		CHL-03				2/7/25	2/7/25
WKU-3403675	Light - E-phone #62 - DSU/Minton	RM	ACK	5		DSU-EXT-88934				2/6/25	2/6/25
WKU-3429600	AA2, 1009, to bright in office	RM	ACK	5		AA2-01-1227				2/13/25	2/13/25
WKU-3431092	Helm 2033 motion detector not working	RM	ACK	5		CHL-02-6721				2/24/25	2/24/25
WKU-3431107	Helm 2024 motion detector not working	RM	ACK	5		CHL-02-6722				2/24/25	2/24/25

# Work Order List

Site: WKUKYUS

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
WKU-3431108	Helm 3017 motion detector not working	RM	ACK	5		CHL-03-6726				2/24/25	2/24/25
WKU-3431109	Helm 3010 motion detector not working	RM	ACK	5		CHL-03-6723				2/24/25	2/24/25
WKU-3431111	Helm 3016 motion detector not working	RM	INPRG	5		CHL-03-6724				2/24/25	2/24/25
WKU-3431116	Gray GMC van needs new tires	PRO	INPRG	5		SWH-01				2/17/25	2/18/25
WKU-3431155	GARH 3rd floor office suite , there are several stained and damaged ceiling tiles and leaks that has the occupant concerned about mold and respiratory concerns. 3037 and 3038.	RM	ACK	5		GRH-03				2/25/25	2/25/25
WKU-3477332	5 floor outlets cover broken or missing in Helm	RM	ACK	5		CHL-02				3/3/25	3/3/25
WKU-3523601	GRH 3029 - window condensation	RM	ACK	5		GRH-01-2111				3/5/25	3/5/25
WKU-3598772	Cravens 502 water from rain	RM	ACK	5		CGC-05-027				4/7/25	4/7/25
WKU-3599046	ISV5/Colonial Court #5 GFCI Issue	RM	ACK	5		CC4-01				4/10/25	4/10/25
WKU-3599062	Water leaked into Cravens 502 from rain	RM	ACK	5		CGC-05-027				4/10/25	4/10/25
WKU-3599112	Cravens 8th floor /806 water leak	RM	ACK	5		CGC-08-027				4/11/25	4/11/25
WKU-3599975	Diddle- Jaguar Ride on need wheels replaced. (Wheels are in the cage) first fl ramp by 3	RM	ACK	5		AA1-01				4/9/25	4/16/25
WKU-3600020	Crack in restroom floor	RM	ACK	5		HCIC-01-838				4/16/25	4/16/25
WKU-3675736	DO NOT ROUTE YET - The curb, outside of DFM by the back gate has a piece broken off.	RM	ACK	5		PPB-EXT-00041				5/8/25	5/8/25
WKU-3676271	Ceiling Tiles	RM	ACK	5		PPB-01				5/19/25	5/19/25

# Work Order List

Site: WKUKYUS											
Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
WKU-3676819	Smith Stadium East Batteries Depleted	RM	ACK	5		AA2-01				5/27/25	5/27/25
WKU-3676820	Smith Stadium West Batteries Depleted	RM	ACK	5		AA2W-01				5/27/25	5/27/25
WKU-3745164	DO NOT ROUTE - Smith West Doors Malfunctioning	NCW	ACK	5		AA1-01-7254				6/16/25	6/16/25
WKU-3745351	Van Meter door lock needs repaired	RM	ACK	5		VMH-01-126				6/20/25	6/20/25
WKU-3818425	AAC	RM	ACK	5		AAC-02-8222				7/2/25	7/2/25
WKU-3825515	Courtyard gazebo outside of West lobby has structural damage	RM	ACK	5		IED-EXT-00371				7/10/25	7/10/25
WKU-3826637	Sidewalk Collapse	RM	ACK	5		AAC-EXT-48878				7/24/25	7/24/25
WKU-3862136	"NM" - EBS 2127 - Carpet is loose and is bubbled up. This is a tripping hazard.	RM	ACK	5		EBS-02-7006				8/4/25	8/4/25
WKU-3868078	PPB, Stockroom/Office - The stockroom and stockroom office need better lighting. Per Ken, the entire area should have all LED lighting throughout entire area	RM	ACK	5		PPB-01-0002 CL				8/4/25	8/4/25
WKU-3869376	PPB, Paint Shop - The paint shop needs better lighting. Per Ken, all LED lighting throughout the entire shop and add lighting over mop sink	RM	ACK	5		PPB-01-0002				8/4/25	8/4/25
WKU-3905432	Smith East 1st floor- broken paper towel dispenser	RM	ACK	5		AA2W-01-10:				1/9/26	1/9/26
WKU-3905562	Helm 1st fl mens room stall doesn't shut	RM	ACK	5		CHL-01				8/22/25	8/27/25
WKU-3905564	Helm 2nd fl womens room stall doesn't shut	RM	ACK	5		CHL-02				8/22/25	8/27/25
WKU-3905567	Helm 3rd fl mens room stall doesn't close	RM	ACK	5		CHL-03				8/22/25	8/27/25
WKU-3906761	Smith West- 2nd floor Men's restroom Paper Towel Dispenser fell off wall.	PRO	INPRG	5		AA2W-02-20				8/22/25	8/22/25
WKU-3938990	Toilet paper dispenser broke	RM	ACK	5		AA1-01				1/9/26	1/9/26
WKU-4001837	AA2, men's bathroom across from room 1021, toilet paper dispenser broken	RM	ACK	5		AA2-01				1/9/26	1/9/26
WKU-4001976	Helm 3002/3008 room divider doesn't close	RM	ACK	5		CHL-03				9/4/25	9/4/25
WKU-4002192	JRH- 2nd floor women's restroom 1 st stall - toilet papers dispenser falls open when u try to use it. Maybe lock is stripped-	RM	ACK	5		JRH-02				1/9/26	1/9/26
WKU-4002891	Helm floor outlet covers broken	RM	INPRG	5		CHL-02				9/11/25	9/16/25
WKU-4040904	HSB, sign out front is leaning and needs fixed	RM	ACK	5		HSB-01				9/30/25	9/30/25
WKU-4081674	ISV #5/Colonial Court #5 Reoccurring Electric Issue	RM	ACK	5		CC5-01				10/8/25	10/8/25
WKU-4082210	Helm 2nd floor womens room stall door doesn't close	RM	ACK	5		CHL-02				10/16/25	10/16/25
WKU-4159529	Raise cabinets in office G01A	RM	ACK	5		WAB-GR-12073				11/7/25	11/7/25
WKU-4160066	Diddle Weight Room Hand Sanitizer Dispenser	RM	ACK	5		AA1-01				11/12/25	11/12/25
WKU-4160151	JRH, EINSTEIN BAGELS, CEILING IN AREA IS SEVERLY DAMAGED	RM	ACK	5		JRH-01-4870				11/14/25	11/14/25
WKU-4160215	JRH Paper tow dispenser.	RM	ACK	5		JRH-02				1/9/26	1/9/26
WKU-4161471	Break Room	RM	ACK	5		PHAC-01-73:				11/24/25	11/24/25
WKU-4161579	CEC/121/DESK IS COMING APART/NEEDS TIGHTENING/HAS A BAD SQUEAK	RM	ACK	5		CEC-01-1180				11/25/25	11/25/25
WKU-4161793	JJ, Room 114, door locking on both sides and need it to not lock on the inside	RM	ACK	5		JJ-01-01764				12/2/25	12/2/25
WKU-4327816	Powerwashing exterior light globes in Kentucky Building Courtyard	NCW	ACK	5		KYB-EXT-49557				1/20/26	1/20/26
WKU-4402207	KB - part of chair fell off - Backlog4 per Dan	NCW	ACK	5		FSH-04-8016				2/9/26	2/9/26

## Work Order List

Site: WKUKYUS

Work Order	Description	Type	Status	Priority	Lead	Location:	Asset	Job Plan	Parent WO	Schedule Start	Schedule Finish
WKU-753848	Dimmer to be installed in Ken and Angies office 2nd request	PRO	INPRG	5		PPB-01-0004				5/15/25	5/15/25
<b>Number of Records:</b>		83									